



Appendix A – Stage I Summary Technical Memorandum is provided on CD only

URS A-1

URS A-1



TO: Joyel Dhieux, On-Scene Coordinator for EPA - Region VIII

FROM: URS Corporation

CC: Tom Gieck, Remediation Leader, TDCC Representative

Louis Hard, HiTec Plastics, Inc.

DATE: May 1, 2014

SUBJECT: Summary of Stage I Field Activities and Investigation Results

Moline Street PCB Site - 3555 Moline Street, Aurora, Adams County, Colorado

URS Corporation (URS) prepared this technical memorandum on behalf of The Dow Chemical Company (TDCC) to present Stage I field activity results for the Moline Street PCB Site located 3555 Moline Street, Aurora, Colorado (Site). This technical memorandum describes the potential approach and path forward for the polychlorinated biphenyls (PCBs) removal action, and is presented in the following sections:

- 1. Site Background
- 2. Summary of Stage I Field Activities
- 3. Wipe Sample Results
- 4. Soil and Concrete Results and Data Evaluation
- 5. Potential Removal Action Approach
- 6. Attachments
- 7. References

TDCC and URS held a meeting on April 9, 2014 with EPA, HiTec Plastics, Inc. (HiTec), and LT Environmental, Inc. (LTE) to discuss the Stage I investigation preliminary findings, as presented in draft tables and figures. This technical memorandum presents final Stage I investigation results and further details the findings and conclusions, which will be used to determine the PCB removal action scope. URS made minor updates to tables and figures following the April 9th meeting; therefore, the results and attachments contained within this technical memorandum supersede those presented at the meeting.

1.0 SITE BACKGROUND

This Section briefly summarizes the physical conditions, investigative history, and contaminant characteristics of the Site. Greater detail is provided in the *Revised Draft Investigation and Removal Action Work Plan* (Revised Work Plan) that URS submitted on February 28, 2014 (URS 2014). The Site is located in Aurora, Colorado near the southwest corner of the intersection of Smith Road and Moline Street (Figure 1). The Site covers approximately 1.8



acres and includes a building with an address of 3555 Moline Street, as shown in Figure 2. The surrounding properties include commercial and light industrial uses. The building north of the Site has an address of 11380 East Smith Road and is currently owned and occupied by HiTec, which operates a plastics recycling operation. HiTec also purchased the Site building (3555 Moline Street) on February 14, 2014, which has been vacant since 2009.

TDCC constructed the Site building in 1969 and used it for magnesium extrusion operations until 1999 when Timminco Corporation assumed the lease and purchased the operating assets, and Timminco continued operations until they transferred their operations to Mexico in August 2009. Several chemicals were historically used to operate and clean the presses used for magnesium extrusion, including hydraulic oils and solvents. PCBs were present within hydraulic oils until 1979 when the United States government banned their manufacturing, processing, distribution, and use. At least two presses were operated (a 500-ton press and an 1800-ton press), and at least one pit was used for wastes from the press(es).

The investigative and regulatory history is detailed in the Revised Work Plan (URS 2014), and summarized as follows:

- Several environmental consultants conducted a number of Phase I and Phase II investigations at the Site between 1999 and 2013.
- Based on findings from a Phase II that LTE conducted in March 2013 (LTE 2013), EPA contacted TDCC in mid-2013 regarding the Site and a site visit was held on August 14, 2013 between EPA, TDCC, HiTec, URS, and LTE.
- EPA, TDCC, HiTec, and URS participated in multiple conference calls and meetings between August 2013 and October 2013 to scope the PCB removal action.
- URS submitted the *Draft Investigation and* Removal *Action Work Plan* to EPA on October 28, 2013 (URS 2013), after which negotiations took place between EPA, Hi Tec, and TDCC in preparation of The Administrative Settlement Agreement and Order on Consent (Settlement Agreement), which was executed by EPA on January 30, 2014.
- EPA gave URS verbal approval on February 13, 2014 to commence Stage I investigation activities and URS submitted the Revised Work Plan on February 28, 2014 (URS 2014), which EPA approved on March 24, 2014.

The Revised Work Plan addresses the work outlined for TDCC in the Settlement Agreement, specifically to address PCBs in soil. The removal action objective specified achieving clean up levels of 25 parts per million (ppm) within the top foot of soil and/or concrete, and a cleanup level of 100 ppm in soil deeper than 1 foot. The Revised Work Plan specified conducting the work in two stages as follows:

• Stage I includes additional Site investigation activities to better understand the nature and extent of contamination, which will assist in planning the removal action.

2

• Stage II includes demolition, excavation, backfilling, and restoration activities.



This technical memorandum summarizes Stage I field activities and results. It also describes the proposed removal action approach and path forward. A Stage II Work Plan will be prepared prior to commencing removal activities, as discussed in Section 5.

2.0 SUMMARY OF STAGE I FIELD ACTIVITIES

This section summarizes Stage I field activities, which included locating utilities, conducting an asbestos building inspection, wipe sampling, drilling and soil sampling, and surveying. Upon EPA's approval to proceed, URS began subcontractor procurement and preparation activities, including notifying the Utility Notification Center of Colorado (UNCC) on February 20, 2014. Another utility location ticket was opened on March 12, 2014 in the event of delayed drilling activities.

2.1 Asbestos Building Inspection

URS contracted Herron Enterprises USA, Inc. (Herron) to perform the asbestos building inspection, which Herron conducted on February 24, 2014. Samples for asbestos analysis were collected from the Site building and the building was evaluated by Herron's Colorado Certified Asbestos Building Inspector (CABI). Herron conducted a standard building asbestos inspection in Buildings A, B, C, and F, as they may be considered for demolition (building lettering is included on Figure 3) and a limited asbestos evaluation of the floor only in Buildings D, E, G, H, and I, as they are not considered for demolition, but were subject to disturbance during drilling and excavation activities. Results indicated that asbestos containing material (ACM) was not present within inspected areas, with the exception of the mastic used for the floor tile in Building G. Therefore, no investigation borings were located in Building G. Herron's asbestos building inspection report is included as Attachment A.

2.2 Wipe Sampling

Concurrent with the asbestos building inspection, URS collected wipe samples for PCB analysis from the ceiling, walls, and floors of Buildings B through I, as shown in Figure 3. URS collected wipe samples from areas having the greatest visible staining and/or dust to conservatively evaluate the possible PCB concentrations. URS collected a total of 32 wipe samples (including quality control samples), 27 of which URS analyzed using a Dexsil field lab kit for PCB 1242, as shown in Table 1 and discussed in Section 3. URS submitted five wipe samples to TestAmerica, an analytical laboratory in Arvada, Colorado, as confirmation samples for laboratory analysis of nine aroclors, as shown in Table 2 and discussed in Section 3. Preliminary PCB results from wipe samples indicated that investigation work could proceed without upgrading to Occupational Safety and Health Administration (OSHA) Level C Personal Protective Equipment (PPE) for the field crew, as long as dust levels were properly managed per the Health and Safety Plan (HASP) included in the Revised Work Plan (URS 2014). During wipe sampling, URS also collected two solid samples of material from two small surficial piles of dust/dirt inside Building C to evaluate



the presence of PCBs in surficial material and dust in the building, as shown in Table 3 and discussed in Section 3.

2.3 Drilling and Subsurface Characterization

Diversified Underground, Inc. conducted a private utility locate on March 14, 2014. URS contracted Alpine Remediation, Inc. (Alpine) to perform concrete coring and direct push technology (DPT) drilling services, which began on March 17, 2014. The DPT rig was equipped with standard 2-inch diameter, 5-foot long, continuous stainless steel samplers with clear plastic liners. URS logged retrieved soil cores for lithologic conditions, color, staining and/or odor, moisture content, other pertinent features, and field screened the samples using a calibrated photoionization detector (PID) to detect total volatile organic vapors. Soil cores were classified via the Unified Soil Classification System (USCS) and documented on soil boring logs, as included in Attachment B. Attachment C includes select photographs from the Stage I activities.

URS conducted drilling and sampling activities between March 17 and 20, 2014 to retrieve soil cores from 52 investigation locations, as shown in Table 4 and on Figure 4. The URS field manager identified the investigation locations with concurrence from the URS project manager and the EPA On-Scene Coordinator. Investigation locations were selected to penetrate through heavily stained areas and/or cracks and seams, assuming these locations were the most likely points of potential release to subsurface soils. URS originally proposed 37 investigation locations in the Revised Work Plan; however, URS added investigation locations based on field observations of surface conditions, subsurface conditions, and/or field screening results.

The 52 investigation locations included:

- Four (4) grab sample locations (e.g., shallow samples retrieved using hand tools) outside and adjacent to the southern wall of the building;
- Two (2) drilled locations outside and north of the building; and
- Forty-six (46) locations drilled inside of the building.

Ventilation management measures (i.e., a series of fans and exhaust tubing) were put in place during indoor drilling to control exhaust from the drill rig. Soil samples were collected from each of the 52 investigation locations, except for SB-19 where the starbit became stuck in the concrete and could not be removed. Soil screening samples were analyzed with the field lab kit for PCB-1242, as presented in Table 5 and discussed in Section 4. A portion of the soil samples analyzed by the field lab kit (approximately 20 percent) were submitted as confirmation samples to TestAmerica for laboratory analysis of the 9 aroclors, as shown in Table 6 and discussed in Section 4.

Of the 46 indoor investigation locations, the concrete was too thick to core through at 6 locations, having a thickness greater than 1-foot, and a starbit drilling technique was used to penetrate through the concrete. At these 6 locations, the concrete thicknesses varied from 2.5 to



5 feet thick. Alpine successfully cored through the concrete slab at the remaining 40 indoor locations and boreholes were subsequently advanced via DPT drilling, with the exception of one location (SB-51) where a hand auger was used due to restricted drill rig access (low ceiling height). Alpine wetted the concrete during coring and starbit drilling with treated water to mitigate dust generation; however, ventilation measures and respirators were used as additional controls and workers protection. The concrete thickness was measured at cored locations and typically ranged between 5 to 8 inches thick, as illustrated on Figure 5. Stained portions of 40 of the concrete cores were submitted to TestAmerica for laboratory analysis of the 9 aroclors, as shown in Table 7.

Of the 47 drilled locations (52 less the 4 grab samples and one hand auger sample), 40 were advanced to 5 feet below ground surface (bgs), or the top of the concrete slab, and 7 were advanced to 10 feet bgs (i.e., SB-25, -31, -45, -46, -47, -50, and -52). Boreholes were abandoned with wetted bentonite chips and patched with concrete. Investigation locations and other Site features (i.e., building corners and estimated pit and press concrete footprints) were surveyed on March 25 and 26, 2014, marking completion of Stage I field activities. URS received the laboratory results from TestAmerica on April 3, 2014.

3.0 WIPE SAMPLE RESULTS

Tables 1 and 2 present the wipe sample results from the field test kits and TestAmerica, respectively, with sample locations shown on Figure 3. In addition to having undergone a quality control review at TestAmerica, a URS chemist conducted an independent quality control review of the analytical results for the five confirmation samples. The forms documenting this review, the laboratory reports, and the qualified data sheets are included in Attachment D.

3.1 Surface Wipe Results

In general, the field test kit results are significantly higher than laboratory analytical results. The field test kit results ranged from 9.65 to 2,406 micrograms per square decimeter (μ g/100 cm²), with an average concentration of approximately 649 μ g/100 cm². Conversely, the analytical laboratory results ranged from 0.38 to 57 μ g/100 cm², with an average concentration of approximately 15 μ g/100 cm². The field test kits detected any organic chloride present on the wipe sample and then calculated the concentration of PCB-1242 by dividing the chloride concentration by 42 percent. This approach assumes that 100 percent of the organic chloride present is attributed to PCB-1242 and is likely the reason for the poor correlation observed between analytical results and field results (Table 2).

EPA guidance (EPA, 1990) specifies that industrial indoor surfaces must be cleaned to total PCB concentrations of $10 \mu g/100 \text{ cm}^2$ or to $100 \mu g/100 \text{ cm}^2$ with encapsulation, as confirmed by post-cleanup wipe sampling. The field test kit PCB results from this Stage I investigation indicate that nearly the entire building would need to be cleaned; however, these data are likely biased



high due to the presence of organic chloride unrelated to PCBs. Analytical results from 2 of the 5 confirmation wipe samples (from the ceiling in Building D and the wall in Building H) exceeded the $10 \,\mu\text{g}/100 \,\text{cm}^2$ threshold, whereas results from the other 3 samples indicated that action would not be necessary.

Due to the variability between the field test kit and fixed laboratory analytical results, TDCC cannot confidently delineate the portions of the building that require cleaning. Furthermore, sample results likely overestimate concentrations representative of their respective building portions as samples were selectively taken from surfaces with the greatest visible staining and dust. Although there is some uncertainty due to inconsistency between field test kit and laboratory results, it can be reasonably concluded from the data that portions of the building will need to be cleaned before the removal action is complete. Additional wipe sampling will be conducted following completion of excavation and restoration activities. Future wipe samples will be submitted for fixed laboratory analysis only and will not be analyzed with the field test kit because of the assumed measurement interference with other sources of organic chloride.

3.2 Surficial Material Sample Results

During the wipe sampling, surficial material on the floor comprised primarily of dust, dirt, and small debris was collected from two locations in Building C and submitted for laboratory analysis, as presented on Table 3. Surficial material collected from a small pile located near the entry to Building D had minor detections of PCBs below the surficial action level of 25 ppm. Surficial material collected in the southwest region of Building C in the vicinity of the former compressors was oily and likely contained other chemicals (e.g., petroleum hydrocarbons) resulting in matrix interference. The interference necessitated greater dilutions during sample analysis, resulting in higher reporting limits for this sample. Nevertheless, total PCBs were not detected above 25 ppm in this material.

4.0 SOIL AND CONCRETE RESULTS AND DATA EVALUATION

Most boreholes were advanced to 5 feet bgs with several boreholes extending to 10 feet bgs. In general, the upper 5 to 6 feet of soil was classified as relatively plastic silts and clays, which were underlain by sands with little fine-grained material. Gray to black staining was observed in 23 borings, with varying heavy-range hydrocarbon odors observed in a portion of these. Because this investigation was limited to relatively shallow soils, saturated soil conditions were not encountered. Attachment B includes boring logs and Attachment C includes photographs of retrieved soil cores.

URS collected soil samples from each of the 52 investigation locations (except SB-19), which the field geologist/engineer selected based on field observations of surface conditions, subsurface conditions, and/or field screening results (Table 4 and Figure 4). URS made 87 soil measurements and 7 concrete dust measurements using the field test kit (Table 5). A total of 20



soil samples and 40 concrete samples were submitted for laboratory analysis of the 9 aroclors (Tables 6 and 7, respectively). A URS chemist conducted an independent quality control review of the soil and concrete analytical data. The data validation report associated with this review, the laboratory reports, and the qualified data sheets are included in Attachment D. A majority of the results for soil samples were flagged due to considerable laboratory dilutions required because of high analyte concentrations and/or matrix interferences.

4.1 Soil Results

The soil results are summarized as follows:

- Field test kit results for the 87 soil samples ranged from 1.5 to 3,563 ppm, with a median soil concentration of approximately 5.8 ppm (Table 5).
- Of the 20 soil confirmation samples, four detected PCBs with concentrations ranging from 1.4 to 7,900 mg/kg, two of which exceeded respective cleanup levels (Table 6).
- Of the sixteen (16) soil confirmation samples that did not detect PCBs, detection limits for total PCBs ranged from 0.003 to 2,900 milligrams per kilogram (mg/kg) or ppm, with a median detection limit of 35 mg/kg (Table 6). Detection limits for the 6 samples without detections are above the respective cleanup levels of 25 ppm (0 to 1foot bgs) and 100 ppm (below 1 foot bgs) and are identified as potential exceedances. For planning purposes, potential exceedances are treated as true exceedances in delineating the removal area, as discussed in Section 5.

In general, there is variability between field test kit and analytical results, with the field test kit results biased low in some samples, matching analytical results well in some, and being biased high in other samples. Although there is not a strong correlation between the field test kit and laboratory results, there is agreement for each of the 20 soil samples between whether the material exceeds a cleanup level (with the exception of sample of the surficial material at SB 31). Therefore, the field test kit results can be reasonably used as a qualitative screening method (i.e., PCB presence and concentration order of magnitude) for delineating the presence of PCBs and estimating exceedance areas.

Field test kit and analytical results were compared against the cleanup levels of 25 ppm in the upper foot and 100 ppm below 1 foot bgs to identify exceedance areas, as shown on Figure 4. Eight investigation locations were identified to have PCB soil contamination above cleanup levels (assuming that SB-19 would have elevated soil concentrations given its elevated concrete concentrations) in portions of Buildings C, D, and F. The remaining 44 sample locations did not contain PCB concentrations above cleanup levels, indicating that soil beneath Buildings A, B, E, H, and I, as well as outside of the warehouse, meets cleanup levels and would not need to be addressed during the removal action (Figure 4). Section 5.0 discusses delineated areas for soil removal.



4.2 Concrete Results

The concrete results are summarized as follows:

- Field test kit results for the 7 concrete dust samples ranged from 1.88 to 1,162 ppm, with a median concentration of approximately 10.5 ppm (Table 5).
- Each of the 40 concrete samples submitted for laboratory analysis detected total PCBs, with concentrations ranging from 0.067 to 3,900 mg/kg and a median concentration of 1.55 mg/kg (Table 7).
- Eight (8) concrete samples exceeded the cleanup level of 25 ppm (assuming SB-19 is included based on its field test kit result) in portions of Buildings C and D, as shown on Figure 5.

Overall, concrete in Buildings A, B, E, F, H, and I did not exceed the cleanup level for total PCBs and thus should not need to be addressed during the removal action. Section 5.0 discusses delineated areas for concrete removal.

5.0 POTENTIAL REMOVAL ACTION APPROACH

Stage I results were used in conjunction with historical results (presented on Figure 6) to evaluate soil and concrete contamination. Figure 7 presents results for locations that had one or more PCB action level exceedance and indicates the estimated depth interval of contamination. URS used this information to delineate the horizontal and vertical extent of soil and concrete contamination, as shown in Figure 8. Areas for concrete sawcutting were identified based on concrete results, the approximate soil removal extent, and ease of earthworking activities, as shown on Figure 8. In areas where analytical or field test kit results were not obtained, the removal area was delineated based on a conceptual understanding of potential releases or sources of contamination.

For example, upon review of historical documents in conjunction with field observations and Stage I results, URS believes that hydraulic oils containing PCBs leaked around the perimeter of the base of the press pit at the joint between the stem wall and pit slab, to a depth of at least 6 feet bgs. Based on historical inspections of the pit, the concrete slab (with a base of 4 feet bgs) is believed to be saturated with oils, and therefore, likely will need to be removed. Upon further review of the historical documents along with the Stage I results, URS believes that the press pit was located approximately 30 feet farther to the east than estimated in the Revised Work Plan (URS 2014).

The Stage II work plan will detail the planned removal action activities and is scheduled for submittal in early May 2014. The following is a preliminary list of Stage II activities:

- HiTec removes Building A (completed April 2014)
- HiTec removes material near Buildings B and C



- URS and their subcontractor (hereafter referred to collectively as URS) hang plastic sheeting between Buildings D and E, and Buildings E and F
- URS removes Building C
- URS sawcuts concrete in delineated areas
- URS excavates contaminated soils and collects confirmation samples
- Upon achieving soil concentrations below cleanup levels along the sidewalls and base of the excavation, URS surveys excavations
- URS backfills and compacts (with compaction testing) excavation areas
- URS places concrete over excavated areas and surveys final grade
- URS cleans designated portions of building
- URS conducts final wipe sampling of building

Presently, URS is finalizing the PCB removal action bid documents for release in early May 2014. Upon receipt of subcontractor bids, URS will select a subcontractor to perform the work. The estimated project schedule is shown in Figure 9 and anticipates that Stage II activities would commence in early July 2014 and conclude by late September 2014.

6.0 ATTACHMENTS

The following attachments are included with this technical memorandum:

•	Table 1	Field Test Kit Results for Wipe Samples
•	Table 2	Analytical Laboratory Results for Wipe Samples
•	Table 3	Analytical Laboratory Results for Solid Surficial Material
•	Table 4	Location Information for Stage I Investigation Borings
•	Table 5	Field Test Kit Results for Soil Screening Samples
•	Table 6	Analytical Laboratory Results for Soil Confirmation Samples
•	Table 7	Analytical Laboratory Results for Concrete Samples
•	Figure 1	Site Location
•	Figure 2	Site Vicinity
•	Figure 3	Wipe Sample Locations
•	Figure 4	Soil Sample Locations and Exceedances
•	Figure 5	Concrete Locations, Exceedances, and Thickness
•	Figure 6	PCB Results from Previous Investigations
•	Figure 7	Stage I PCB Results in Soil and Concrete – March 2014
•	Figure 8	Potential Removal and Demolition Areas
•	Figure 9	Project Schedule
•	Attachment A	Asbestos Building Inspection Report – 2/24/2014
•	Attachment B	Stage I Field Documentation



- Attachment C Photographic Log
- Attachment D Data Validation and Laboratory Reports

7.0 REFERENCES

- LT Environmental Inc. (LTE). 2013. Limited Phase II Environmental Site Assessment. May 14.
- URS Corporation (URS). 2013. Draft Investigation and Removal Action Work Plan, Smith Road and Moline Street Site, Aurora, Colorado. October 28.
- URS. 2014. Revised Draft Investigation and Removal Action Work Plan, Moline Street PCB Site, Aurora, Colorado. February 28.
- United States Environmental Protection Agency (EPA). 1990. *Guidance on Remedial Actions for Superfund Sites with PCB Contamination*. Document 540/G-90/007. August.

May 1, 2014

STAGE I SUMMARY TECHNICAL MEMORANDUM Moline Street PCB Site

TABLES

table 1 Field Test Kit Results for Wipe Samples

Stage I Investigation, Moline Street PCB Site

		Collection	Field Test Kit PCB	Field Test Kit
Sample	Sample	Height	1242 Results	Chloride Results
Number	Identification	(feet ags)	$(\mu g/100 \text{ cm}^2)$	$(\mu g/100 \text{ cm}^2)$
1	D-C1-15.5	15.5	763	320
2	D-C1-15.5-FD	15.5	2406	1010
3	D-W1-5	5	779	335
4	D-F1-0	0	1115	468
5	B-C1-13.5	13.5	1315	552
6	B-W1-2	2	114	48
7	B-F1-0	0	1998	838
8	C-C1-11	11	374	157
9	C-W1-4	4	1787	750
10	C-F1-0	0	5490	2306
11	C-TANK	2	1145	481
12	E-C1-12.5	12.5	229	96.3
13	E-W1-4	4	78.9	33.1
14	E-F1-0	0	2000	84
15	F-C1-12	12	73.9	31
16	F-W1-3	3	78.3	32.9
17	G-C1-9	9	349	146
18	G-W1-4	4	11.7	4.83
19	G-F1-0	0	59.4	24.9
20	H-C1-12.5	12.5	16.0	6.73
21	H-W1-4	4	42.3	17.7
22	H-F1-0	0	629	264
23	I-C1-16.5	16.5	15.2	6.41
24	I-W1-4	4	9.65	4.05
25	I-F1-0	0	815	342
26	I-F1-0-FD	0	408	171
27	F-F1-0	0	272	114

Notes:

 $\mu g/100 \text{ cm}^2 = \text{micrograms per square centimeter}$

ags = above ground surface

FD = field duplicate

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (μg/100 cm²)	Field Test Kit PCB 1242 Result (µg/100 cm ²)
		PCB-1016	< 0.15	
C-WI-4		PCB-1221	< 0.32	1
		PCB-1232	< 0.15	1
		PCB-1242	< 0.27	
	2/24/2014	PCB-1248	< 0.1	1787
C-W1-4	2/24/2014	PCB-1254	0.42 J	1/6/
		PCB-1260	< 0.08	
		PCB-1262	< 0.34	
		PCB-1268	< 0.12	
		Total PCBs	0.42 J	
		PCB-1016	< 0.31	
		PCB-1221	< 0.64	
		PCB-1232	< 0.31	
		PCB-1242	< 0.55	
D-CI-15.5	2/24/2014	PCB-1248	< 0.2	763
D-CI-13.3	2/24/2014	PCB-1254	13	703
		PCB-1260	< 0.16	
		PCB-1262	< 0.67	
		PCB-1268	< 0.24	
		Total PCBs	13	
		PCB-1016	<0.15 UJ	
		PCB-1221	<0.32 UJ	
		PCB-1232	<0.15 UJ	
		PCB-1242	<0.27 UJ	
F-WI-3	2/24/2014	PCB-1248	<0.1 UJ	78.3
1 ,,13	2,21,2011	PCB-1254	0.38 J	. , 6.5
		PCB-1260	<0.08 UJ	
		PCB-1262	<0.34 UJ	
		PCB-1268	<0.12 UJ	
		Total PCBs	0.38 J	
		PCB-1016	<1.5	
		PCB-1221	<3.2	
		PCB-1232	<1.5	
		PCB-1242	<2.7	
H-WI-4	2/24/2014	PCB-1248	<1	42.3
		PCB-1254	57	
		PCB-1260	<0.8	
		PCB-1262	<3.4	
		PCB-1268	<1.2	
		Total PCBs	57	

table 2 Analytical Laboratory Results for Wipe Samples

Stage I Investigation, Moline Street PCB Site

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (μg/100 cm²)	Field Test Kit PCB 1242 Result (µg/100 cm²)
		PCB-1016	< 0.15	
	2/24/2014	PCB-1221	< 0.32	
		PCB-1232	< 0.15	
		PCB-1242	< 0.27	
I-FI-0		PCB-1248	5.4	815
1-11-0		PCB-1254	< 0.12	813
		PCB-1260	< 0.08	
		PCB-1262	< 0.34	
		PCB-1268	< 0.12	
		Total PCBs	5.4	

Notes:

Field laboratory results are generally significantly higher than analytical laboratory results.

It is likely that other sources of organic chlorine may be present in the samples.

bolded values denote detections

 $\mu g/100 \text{ cm}^2 = \text{micrograms per square centimeter}$

PCB = polychlorinated biphenyl

< = analyte was not detected above the specified method detection limit

Validation Flags: J - Estimated, UJ - Estimated Nondetect

table 3 Analytical Laboratory Results for Solid Surficial Material

Stage I Investigation, Moline Street PCB Site

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)	Comment
		PCB-1016	< 0.15	
		PCB-1221	< 0.45	
		PCB-1232	< 0.15	
		PCB-1242	< 0.26	Dust and debris
C-SOIL-	2/24/2014	PCB-1248	3.1 NJ	material on floor of
LIGHT	2/24/2014	PCB-1254	<0.16 UJ	Building C near entry
		PCB-1260	< 0.076	way to Building D
		PCB-1262	< 0.33	
		PCB-1268	< 0.11	
		Total PCBs	3.1	
		PCB-1016	<49	
		PCB-1221	<150	
		PCB-1232	<49	0:1 1:
		PCB-1242	<88	Oily dirt material on floor in southwest
C-SOIL-	2/24/2014	PCB-1248	<54	
DARK	2/24/2014	PCB-1254	<53	corner of Building C near former location of
		PCB-1260	<25	
		PCB-1262	<110	compressors
		PCB-1268	<38	
		Total PCBs	<25	

Notes:

bolded values denote detections

mg/kg = milligrams per kilogram

PCB = polychlorinated biphenyl

ppm = parts per million

< = analyte was not detected above the specified method detection limit

Validation Flags: NJ - Tentatively Identified, UJ - Estimated Nondetect

table 4 Location Information for Stage I Investigation Borings

Stage I Investigation, Moline Street PCB Site

	G 1	State Plane	Coordinates	Ground Surface	Approximate Concrete
Location	Sample	Northing	Easting	Elevation	Thickness
	Type	(feet)	(feet)	(feet amsl)	(inches)
SB-01	DPT	1,704,434.51	3,181,347.95	5,296.89	6
SB-02	DPT	1,704,467.11	3,181,307.72	5,296.79	7
SB-03	DPT	1,704,418.53	3,181,304.47	5,296.88	6
SB-04	DPT	1,704,432.69	3,181,293.86	5,296.95	Not Measured
SB-05	DPT	1,704,445.25	3,181,249.51	5,296.91	6
SB-06	DPT	1,704,416.22	3,181,243.29	5,296.91	6" wood plug
SB-07	DPT	1,704,412.66	3,181,201.06	5,296.76	6
SB-08	DPT	1,704,441.00	3,181,194.31	5,296.89	6
SB-09	DPT	1,704,443.44	3,181,147.81	5,296.90	7
SB-10	DPT	1,704,409.67	3,181,148.19	5,296.92	6
SB-11	DPT	1,704,476.63	3,181,166.80	5,296.58	5
SB-12	DPT	1,704,483.18	3,181,149.37	5,296.56	7
SB-13	DPT	1,704,430.08	3,181,130.32	5,296.82	6
SB-14	DPT	1,704,408.41	3,181,089.99	5,296.88	6
SB-15	Starbit	1,704,447.45	3,181,062.19	5,296.88	36
SB-16	DPT	1,704,421.95	3,181,057.83	5,296.90	2.5
SB-17	DPT	1,704,399.15	3,181,039.02	5,296.84	5
SB-18	DPT	1,704,415.93	3,181,041.06	5,296.88	5
SB-19	Starbit	1,704,443.06	3,181,032.59	5,296.82	>54
SB-20	DPT	1,704,429.90	3,181,027.28	5,296.87	6
SB-21	DPT	1,704,425.31	3,181,040.73	5,296.85	6.5
SB-22	DPT	1,704,422.62	3,181,017.75	5,296.86	6
SB-23	Starbit	1,704,438.36	3,181,005.07	5,296.92	36
SB-24	DPT	1,704,436.21	3,180,999.97	5,296.87	12
SB-25	Starbit	1,704,398.26	3,180,989.41	5,296.85	60
SB-26	DPT	1,704,398.34	3,180,974.12	5,296.84	4
SB-27	DPT	1,704,452.43	3,180,974.90	5,296.82	5
SB-28	DPT	1,704,411.13	3,180,936.90	5,296.79	7
SB-29	Starbit	1,704,446.62	3,180,938.30	5,296.70	36
SB-30	Starbit	1,704,462.58	3,180,938.58	5,296.81	36
SB-31	DPT	1,704,457.97	3,180,969.79	5,296.71	3
SB-32	DPT	1,704,462.59	3,180,981.17	5,296.66	5
SB-33	DPT	1,704,461.76	3,181,070.92	5,296.73	4
SB-34	DPT	1,704,495.74	3,180,975.69	5,295.92	3
SB-35	DPT	1,704,498.37	3,181,297.64	5,296.54	4.5
SB-36	Grab	1,704,388.58	3,180,967.85	5,294.70	
SB-37	Grab	1,704,393.21	3,181,066.67	5,295.49	not applicable - located in
SB-38	Grab	1,704,395.91	3,181,201.22	5,296.16	southern field
SB-39	Grab	1,704,396.51	3,181,273.16	5,295.73	
SB-40	DPT	1,704,464.32	3,180,994.91	5,296.70	4

table 4 Location Information for Stage I Investigation Borings

Stage I Investigation, Moline Street PCB Site

	Sample	State Plane	Coordinates	Ground Surface	Approximate Concrete
Location	Type	Northing (feet)	Easting (feet)	Elevation (feet amsl)	Thickness (inches)
SB-41	DPT	1,704,468.34	3,180,944.56	5,296.77	3.5
SB-42	DPT	1,704,464.45	3,181,011.19	5,296.76	18
SB-43	DPT	1,704,461.03	3,181,025.68	5,296.79	4
SB-44	DPT	1,704,461.13	3,181,048.07	5,296.69	4.5
SB-45	DPT	1,704,443.67	3,181,028.21	5,296.88	8.5
SB-46	DPT	1,704,447.38	3,180,990.21	5,296.86	7
SB-47	DPT	1,704,469.48	3,181,001.29	5,296.68	5
SB-48	DPT	1,704,481.16	3,180,985.04	5,296.36	4
SB-49	DPT	1,704,488.91	3,181,006.35	5,296.20	7
SB-50	DPT	1,704,447.85	3,181,029.53	5,296.86	5
SB-51	Hand Auger	1,704,474.67	3,181,034.27	5,296.60	4
SB-52	DPT	1,704,452.41	3,181,043.78	5,296.83	6.5

Notes:

amsl = above mean sea level

DPT = the sample was retrieved via direct push drilling following slab removal by coring

Grab = the sample was retrived using hand tools (locations were in southern field)

Hand Auger = the sample was retrieved with a hand auger after coring through the slab

SB = soil boring

Starbit = the concrete was too thick for the coring device, therefore, a starbit was attached to the DPT rig

table 5 Field Test Kit Results for Soil Screening Samples

Stage I Investigation, Moline Street PCB Site

Test #	Boring Location	Sample Depth (feet bgs)	Field Test Kit Result PCB 1242 (ppm)	Comment
1	SB-01	1	3.76	
2	SB-02	1	6.09	
3	SB-03	1.5	1.5	
4	3D-03	4.5	4.63	
5	SB-04	1	4.12	
6	SB-05	1	3.34	
7	SB-06	1.5	2.76	
8	SB-07	1.5	2.44	
9	SB-08	1.5	2.57	
10	SB-09	1.5	4.35	
11	SB-10	1	11.9	
12		1.5	25.1	
13	SB-11	1.5	3.39	field duplicate
14		2.5	3.33	
15	SB-12	1.5	4.45	
16	SB-13	1	4.22	
17	SB-14	1.5	3.17	
18	SB-15	0	21	concrete dust
19	SD-13	3.5	2.77	
20	SB-16	1.5	21.9	
21	SB-17	1.5	3.68	
22	SD-17	4.5	2.39	
23	SB-18	1	2.29	
24	SB-19	0	1162	concrete dust
25	SD-19	0	828	concrete dust, field duplicate
26	SB-20	1.5	3.57	
27	SB-21	1	4.55	
28	SB-22	1	5.88	
29	SB-23	0	10.5	concrete dust
30	SD-23	3	3.01	
31	SB-24	1.5	3.51	
32		0	1.88	concrete dust
33	SB-25	5.5	3.34	
34		6.5	3.17	
35		1.5	6.55	
36	SB-26	3	4.76	
37		4.5	6.19	
38	SB-27	1.5	1.58	
39	SB-28	1.5	7.32	
40	SB-29	0	3.55	concrete dust
41	SD-29	3	12.8	

table 5 Field Test Kit Results for Soil Screening Samples

Stage I Investigation, Moline Street PCB Site

Test #	Boring Location	Sample Depth (feet bgs)	Field Test Kit Result PCB 1242 (ppm)	Comment
42	SB-30	0	5.25	concrete dust
43		3	80.6	
44		4	5.89	
45		4	5.59	field duplicate
46		0.5	99	
47	SB-31	1.5	3.28	
48		4.5	8.36	
49	SB-32	1.5	473	
50	SD-32	2.5	4.18	
51	SB-33	1.5	5.17	
52	SB-34	1.5	14.6	
53	SB-35	1.5	2.47	
54	SB-36	1	12.1	outside door
55	SB-37	0	5.55	outside pipe
56	SD-3/	1	2.89	outside pipe
57	CD 20	0	5.71	outside hole
58	SB-38	1	3.22	
59	SB-39	1	4.28	
60		1.5	3563	
61		3	3546	
62	SB-40	4	2017	
63		5	11.1	
64		5	7.11	field duplicate
65	SB-41	1.5	4.91	
66	SB-42	3	7.78	
67	SB-43	3	1899	
68	SD-43	5	9.27	
69	SB-44	4.5	57.7	
70		1.5	13.5	
71		2.5	5.21	
72	SB-45	3.5	12	
73	SD-43	4.5	48.5	
74		5.5	3.03	
75		6.25	13	
76	SB-46	1.5	3.07	
77	ეD-40	4.5	3.92	
78		2	437	
79	SB-47	5	15.2	
80	SD-4/	5	44	
81		9	3.64	
82	SB-48	2	8.49	

table 5 Field Test Kit Results for Soil Screening Samples

Stage I Investigation, Moline Street PCB Site

Test #	Boring Location	Sample Depth (feet bgs)	Field Test Kit Result PCB 1242 (ppm)	Comment
83	SB-49	3.5	Not Measured	Unable to filter, too dense
84	SD-47	4.5	3.56	
85		4	1180	
86	SB-50	5	524	
87		6	187	
88		6	179	field duplicate
89	SB-51	1	9.1	
90		4	15.1	
91	SB-52	5	12.4	
92	SD-32	6	16.1	
93		7	16	
94	SB-Background	1	7.87	collected south of building

Notes:

bolded sample depths indicate that the soil sample was also submitted for laboratory analysis Shaded entries indicate that concentrations either exceed 25 ppm in the upper 1 foot of soil or exceed 100 ppm below 1 foot.

 $bgs = below \ ground \ surface$

ppm = parts per million

 $SB = soil\ boring$

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)	Field Test Kit PCB 1242 Result (ppm)	
		PCB-1016	< 0.0058		
		PCB-1221	< 0.018		
		PCB-1232	< 0.0058		
SB-03-4.5		PCB-1242	< 0.01		
	2/17/2014	PCB-1248	< 0.0064	4.62	
	3/17/2014	PCB-1254	< 0.0063	4.63	
		PCB-1260	< 0.003		
		PCB-1262	< 0.013		
		PCB-1268	< 0.0045		
		Total PCBs	< 0.003		
		PCB-1016	<6.4		
		PCB-1221	<20		
		PCB-1232	<6.4		
		PCB-1242	<11		
CD 11 1 5	2/17/2014	PCB-1248	<120 UJ	25.1	
SB-11-1.5	3/17/2014	PCB-1254	<6.9 UJ	25.1	
		PCB-1260	<3.3		
		PCB-1262	<15		
		PCB-1268	<4.9		
		Total PCBs	<120 U		
		PCB-1016	< 0.023		
		PCB-1221	< 0.069		
		PCB-1232	< 0.023		
		PCB-1242	< 0.041		
SB-20-1.5	2/19/2014	PCB-1248	<0.37 UJ	2.55	
SD-20-1.3	3/18/2014	PCB-1254	<0.025 UJ	3.57	
		PCB-1260	< 0.012		
		PCB-1262	< 0.052		
		PCB-1268	< 0.018		
		Total PCBs	<0.37 U		
		PCB-1016	< 0.0057		
		PCB-1221	< 0.017		
		PCB-1232	< 0.0057		
		PCB-1242	< 0.01		
CD 22 1	3/18/2014	PCB-1248	<0.047 U	5.88	
SB-22-1		PCB-1254	< 0.0062	5.00	
		PCB-1260	< 0.003		
		PCB-1262	< 0.013		
		PCB-1268	< 0.0044		
		Total PCBs	<0.047 U		

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)	Field Test Kit PCB 1242 Result (ppm)	
		PCB-1016	< 0.03		
SD 22 2		PCB-1221	< 0.091		
		PCB-1232	< 0.03		
		PCB-1242	< 0.053		
	2/10/2014	PCB-1248	1.4 NJ	2.01	
SB-23-3	3/19/2014	PCB-1254	<0.032 UJ	3.01	
		PCB-1260	< 0.016		
		PCB-1262	< 0.068		
		PCB-1268	< 0.023]	
		Total PCBs	1.4]	
		PCB-1016	< 0.0055		
		PCB-1221	< 0.017		
		PCB-1232	< 0.0055		
		PCB-1242	< 0.0099]	
SB-24-1.5	3/18/2014	PCB-1248	<0.12 UJ	2.51	
SB-24-1.5		PCB-1254	<0.006 UJ	3.51	
		PCB-1260	< 0.0029		
		PCB-1262	< 0.013		
		PCB-1268	< 0.0043		
		Total PCBs	<0.12 U		
		PCB-1016	<0.0053 UJ		
		PCB-1221	<0.016 UJ		
		PCB-1232	<0.0053 UJ]	
		PCB-1242	<0.0095 UJ		
SB-25-5.5	3/19/2014	PCB-1248	<0.13 UJ	3.34	
SB-23-3.3	3/19/2014	PCB-1254	<0.0058 UJ	3.34	
		PCB-1260	<0.0028 UJ		
		PCB-1262	<0.012 UJ		
		PCB-1268	<0.0041 UJ		
		Total PCBs	<0.13 U		
		PCB-1016	<2.9		
		PCB-1221	<8.8		
		PCB-1232	<2.9		
		PCB-1242	<5.1		
SB-30-3	3/19/2014	PCB-1248	<92 U	80.6	
SB-30-3	3/17/2014	PCB-1254	<3.1	ov.v	
		PCB-1260	<1.5		
		PCB-1262	<6.5		
		PCB-1268	<2.2		
		Total PCBs	<92 U		

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)	Field Test Kit PCB 1242 Result (ppm)
		PCB-1016	< 0.051	
		PCB-1221	< 0.16	
		PCB-1232	< 0.051	
		PCB-1242	< 0.091	
CD 21 0 5	2/19/2014	PCB-1248	< 0.056	99
SB-31-0.5	3/18/2014	PCB-1254	2.7	99
		PCB-1260	< 0.027	
		PCB-1262	< 0.12	
		PCB-1268	< 0.04	
		Total PCBs	2.7	
		PCB-1016	<57	
		PCB-1221	<170	
		PCB-1232	<57	
		PCB-1242	<100	
SB-32-1.5	3/18/2014	PCB-1248	<2900 UJ	473
SB-32-1.3	3/10/2014	PCB-1254	<62 UJ	473
		PCB-1260	<30	
		PCB-1262	<130	
		PCB-1268	<44	
		Total PCBs	<2900 U	
		PCB-1016	<120	
		PCB-1221	<370	
		PCB-1232	<120	
		PCB-1242	<210	
SB-40-3	3/18/2014	PCB-1248	7900 NJ	3546
52 10 3	3/10/2011	PCB-1254	<130 UJ	0010
		PCB-1260	<62	
		PCB-1262	<270	
		PCB-1268	<93	
		Total PCBs	7900	
		PCB-1016	<53	
SB-40-4		PCB-1221	<160	
		PCB-1232	<54	
		PCB-1242	<96	
	3/18/2014	PCB-1248	<2700 UJ	2017
		PCB-1254	<58 UJ	
		PCB-1260	<28	
		PCB-1262	<120	
		PCB-1268	<42	
		Total PCBs	<2700 U	

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)	Field Test Kit PCB 1242 Result (ppm)
		PCB-1016	<30	
		PCB-1221	<92	
		PCB-1232	<30	
		PCB-1242	<54	
SB-43-3	3/20/2014	PCB-1248	<1100 UJ	1899
SD-45-5	5/20/2014	PCB-1254	<32 UJ	
		PCB-1260	<16	
		PCB-1262	<68	
		PCB-1268	<23	
		Total PCBs	<1100 U	
		PCB-1016	<62	
		PCB-1221	<190	
		PCB-1232	<63	
		PCB-1242	<110	
SB-43-3-FD	3/20/2014	PCB-1248	<2800 UJ	1899
3D-43-3-1D	3/20/2014	PCB-1254	<68 UJ	1077
		PCB-1260	<32	
		PCB-1262	<140	
		PCB-1268	<48	
		Total PCBs	<2800 U	
		PCB-1016	<1.1	
		PCB-1221	<3.3	
		PCB-1232	<1.1	
		PCB-1242	<1.9	
SB-44-4.5	3/20/2014	PCB-1248	<27 UJ	57.7
	3/20/2011	PCB-1254	<1.2 UJ	
		PCB-1260	< 0.56	
		PCB-1262	<2.5	
		PCB-1268	< 0.84	
		Total PCBs	<27 U	
		PCB-1016	<1.1	
		PCB-1221	<3.3	
SB-45-4.5		PCB-1232	<1.1	
		PCB-1242	<1.9	
	3/19/2014	PCB-1248	<43 UJ	48.5
	2, 2, 2011	PCB-1254	<1.2 UJ	
		PCB-1260	< 0.56	
		PCB-1262	<2.5	
	<u> </u>	PCB-1268	<0.84	
		Total PCBs	<43 U	

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)	Field Test Kit PCB 1242 Result (ppm)
		PCB-1016	<120	
		PCB-1221	<360	
		PCB-1232	<120	
		PCB-1242	<210	
SB-47-2	3/20/2014	PCB-1248	7400 NJ	437
SB-47-2	3/20/2014	PCB-1254	<130 UJ	437
		PCB-1260	<60	
		PCB-1262	<260	
		PCB-1268	<90	
		Total PCBs	7400	
		PCB-1016	< 0.056	
		PCB-1221	< 0.17	3.64
		PCB-1232	< 0.057	
		PCB-1242	< 0.1	
SB-47-9	3/20/2014	PCB-1248	<2.2 UJ	
SD-47-7	3/20/2014	PCB-1254	<0.061 UJ	
		PCB-1260	< 0.029	
		PCB-1262	< 0.13	
		PCB-1268	< 0.044	
		Total PCBs	<2.2 U	
		PCB-1016	<5.3	
		PCB-1221	<16	
		PCB-1232	<5.3	
SB-50-5		PCB-1242	<9.5	
	3/20/2014	PCB-1248	<250 UJ	524
	3/20/2014	PCB-1254	<5.7 UJ	<i>32</i> T
		PCB-1260	<2.8	
		PCB-1262	<12	
		PCB-1268	<4.1	
		Total PCBs	<250 U	

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)	Field Test Kit PCB 1242 Result (ppm)
		PCB-1016	< 0.056	
		PCB-1221	< 0.17	
	3/20/2014	PCB-1232	< 0.056	
		PCB-1242	< 0.1	
SB-52-5		PCB-1248	<2.1 UJ	12.4
SD-32-3		PCB-1254	<0.06 UJ	12.4
		PCB-1260	< 0.029	
		PCB-1262	< 0.13	
		PCB-1268	< 0.043	
		Total PCBs	<2.1 U	

Notes:

bolded values are detections; shaded entries indicate that concentrations either exceed 25 ppm in the upper 1 foot of soil or exceed 100 ppm below 1 foot. Yellow denotes a potential exceedance, as the detection limit exceeded the action level, whereas gray denotes a detected exceedance.

mg/kg = milligrams per kilogram

PCB = polychlorinated biphenyl

ppm = parts per million

< = analyte was not detected above the specified method detection limit Validation Flags: NJ - Tentatively Identified, U - Nondetect, UJ - Estimated Nondetect

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	< 0.11
		PCB-1221	< 0.33
		PCB-1232	< 0.11
		PCB-1242	< 0.19
SB-03-0	3/17/2014	PCB-1248	3.1 NJ
SD-03-0	3/17/2014	PCB-1254	<0.12 UJ
		PCB-1260	< 0.055
		PCB-1262	< 0.24
		PCB-1268	< 0.083
		Total PCBs	3.1
		PCB-1016	< 0.1
		PCB-1221	< 0.31
		PCB-1232	< 0.1
		PCB-1242	< 0.18
GD 07 0	2/17/2014	PCB-1248	<0.11 UJ
SB-05-0	3/17/2014	PCB-1254	4.3 NJ
		PCB-1260	< 0.053
		PCB-1262	< 0.23
		PCB-1268	< 0.079
		Total PCBs	4.3
		PCB-1016	< 0.048
		PCB-1221	< 0.15
		PCB-1232	< 0.049
		PCB-1242	< 0.087
an oco	2/17/2014	PCB-1248	1.3
SB-06-0	3/17/2014	PCB-1254	< 0.053
		PCB-1260	< 0.025
		PCB-1262	< 0.11
		PCB-1268	< 0.038
		Total PCBs	1.3
		PCB-1016	< 0.0048
		PCB-1221	< 0.015
	3/17/2014	PCB-1232	< 0.0048
		PCB-1242	< 0.0086
CD 11.0		PCB-1248	0.18 NJ
SB-11-0		PCB-1254	<0.0052 UJ
		PCB-1260	< 0.0025
		PCB-1262	< 0.011
		PCB-1268	< 0.0037
		Total PCBs	0.18

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	< 0.0053
		PCB-1221	< 0.016
		PCB-1232	< 0.0053
		PCB-1242	< 0.0095
SB-12-0	3/17/2014	PCB-1248	0.28 NJ
SB-12-0	3/17/2014	PCB-1254	<0.0057 UJ
		PCB-1260	< 0.0028
		PCB-1262	< 0.012
		PCB-1268	< 0.0041
		Total PCBs	0.28
		PCB-1016	< 0.053
		PCB-1221	< 0.16
		PCB-1232	< 0.053
		PCB-1242	< 0.095
GD 12.0	2/17/2014	PCB-1248	2.3 NJ
SB-13-0	3/17/2014	PCB-1254	<0.057 UJ
		PCB-1260	< 0.027
		PCB-1262	< 0.12
		PCB-1268	< 0.041
		Total PCBs	2.3
		PCB-1016	< 0.48
		PCB-1221	<1.5
		PCB-1232	< 0.49
		PCB-1242	< 0.87
GD 14.0	2/17/2014	PCB-1248	7.2 NJ
SB-14-0	3/17/2014	PCB-1254	<0.52 UJ
		PCB-1260	< 0.25
		PCB-1262	<1.1
		PCB-1268	< 0.37
		Total PCBs	7.2
		PCB-1016	< 0.0053
		PCB-1221	< 0.016
CD 15 0	2/17/2014	PCB-1232	< 0.0053
		PCB-1242	< 0.0095
		PCB-1248	0.14 NJ
SB-15-0	3/17/2014	PCB-1254	<0.0057 UJ
		PCB-1260	< 0.0028
		PCB-1262	< 0.012
		PCB-1268	< 0.0041
		Total PCBs	0.14

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	< 0.0054
		PCB-1221	< 0.017
		PCB-1232	< 0.0055
		PCB-1242	< 0.0097
SD 16.0	2/17/2014	PCB-1248	0.067 NJ
SB-16-0	3/17/2014	PCB-1254	<0.0059 UJ
		PCB-1260	< 0.0028
		PCB-1262	< 0.012
		PCB-1268	< 0.0042
		Total PCBs	0.067
		PCB-1016	< 0.0049
		PCB-1221	< 0.015
		PCB-1232	< 0.0049
		PCB-1242	< 0.0087
GD 17 0	2/10/2014	PCB-1248	<0.0054 UJ
SB-17-0	3/18/2014	PCB-1254	0.25 NJ
		PCB-1260	< 0.0025
		PCB-1262	< 0.011
		PCB-1268	< 0.0038
		Total PCBs	0.25
		PCB-1016	< 0.02
		PCB-1221	< 0.061
		PCB-1232	< 0.02
		PCB-1242	< 0.036
GD 10.0	3/18/2014	PCB-1248	0.66 NJ
SB-18-0		PCB-1254	<0.022 UJ
		PCB-1260	< 0.01
		PCB-1262	< 0.045
		PCB-1268	< 0.015
		Total PCBs	0.66
		PCB-1016	<0.1
		PCB-1221	< 0.31
	2/10/2014	PCB-1232	<0.1
		PCB-1242	< 0.18
SD 20.0		PCB-1248	<0.11 UJ
SB-20-0	3/18/2014	PCB-1254	2.3 NJ
		PCB-1260	< 0.052
		PCB-1262	< 0.23
		PCB-1268	< 0.078
		Total PCBs	2.3

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	< 0.0053
		PCB-1221	< 0.016
		PCB-1232	< 0.0053
		PCB-1242	< 0.0094
SB-21-0	3/17/2014	PCB-1248	0.2 NJ
SD-21-0	3/17/2014	PCB-1254	<0.0057 UJ
		PCB-1260	< 0.0027
		PCB-1262	< 0.012
		PCB-1268	< 0.0041
		Total PCBs	0.2
		PCB-1016	< 0.0052
		PCB-1221	< 0.016
		PCB-1232	< 0.0052
		PCB-1242	< 0.0093
SB-22-0	3/18/2014	PCB-1248	0.13 NJ
SD-22-0	3/10/2014	PCB-1254	<0.0056 UJ
		PCB-1260	< 0.0027
		PCB-1262	< 0.012
		PCB-1268	< 0.004
		Total PCBs	0.13
		PCB-1016	< 0.0054
		PCB-1221	< 0.016
		PCB-1232	< 0.0054
		PCB-1242	< 0.0096
SB-23-0	3/19/2014	PCB-1248	0.3 NJ
SD-23-0	3/19/2014	PCB-1254	<0.0058 UJ
		PCB-1260	< 0.0028
		PCB-1262	< 0.012
		PCB-1268	< 0.0042
		Total PCBs	0.3
		PCB-1016	< 0.53
		PCB-1221	<1.6
	3/18/2014	PCB-1232	< 0.53
		PCB-1242	< 0.94
SB-24-0		PCB-1248	19 NJ
SD-24-U		PCB-1254	<0.57 UJ
		PCB-1260	< 0.27
		PCB-1262	<1.2
		PCB-1268	< 0.41
		Total PCBs	19

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	<0.0052 UJ
		PCB-1221	<0.016 UJ
		PCB-1232	<0.0052 UJ
		PCB-1242	<0.0093 UJ
SB-25-0	3/19/2014	PCB-1248	0.24 NJ
SD-23-0	3/19/2014	PCB-1254	<0.0056 UJ
		PCB-1260	<0.0027 UJ
		PCB-1262	<0.012 UJ
		PCB-1268	<0.004 UJ
		Total PCBs	0.24
		PCB-1016	<5
		PCB-1221	<15
		PCB-1232	<5
		PCB-1242	<8.9
GD 26 0	2/10/2014	PCB-1248	130 NJ
SB-26-0	3/18/2014	PCB-1254	<5.4 UJ
		PCB-1260	<2.6
		PCB-1262	<11
		PCB-1268	<3.9
		Total PCBs	130
		PCB-1016	< 0.52
		PCB-1221	<1.6
		PCB-1232	< 0.52
		PCB-1242	< 0.93
GD 27 0	2/10/2014	PCB-1248	13 NJ
SB-27-0	3/18/2014	PCB-1254	<0.56 UJ
		PCB-1260	< 0.27
		PCB-1262	<1.2
		PCB-1268	<0.4
		Total PCBs	13
		PCB-1016	< 0.005
		PCB-1221	< 0.015
	3/18/2014	PCB-1232	< 0.0051
		PCB-1242	< 0.009
CD 20 0		PCB-1248	0.26 NJ
SB-28-0		PCB-1254	<0.0055 UJ
		PCB-1260	< 0.0026
		PCB-1262	< 0.011
		PCB-1268	< 0.0039
		Total PCBs	0.26

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	< 0.026
		PCB-1221	< 0.079
		PCB-1232	< 0.026
		PCB-1242	< 0.046
SB-29-0	3/19/2014	PCB-1248	0.28 NJ
3D-29-0	3/19/2014	PCB-1254	<0.028 UJ
		PCB-1260	< 0.013
		PCB-1262	< 0.059
		PCB-1268	< 0.02
		Total PCBs	0.28
		PCB-1016	<0.0052 UJ
		PCB-1221	<0.016 UJ
		PCB-1232	<0.0052 UJ
		PCB-1242	<0.0093 UJ
SB-30-0	3/19/2014	PCB-1248	0.12 NJ
SB-30-0	3/19/2014	PCB-1254	<0.0057 UJ
		PCB-1260	<0.0027 UJ
		PCB-1262	<0.012 UJ
		PCB-1268	<0.004 UJ
		Total PCBs	0.12
		PCB-1016	< 0.051
		PCB-1221	< 0.16
		PCB-1232	< 0.051
		PCB-1242	< 0.091
SB-31-0	2/19/2014	PCB-1248	1.3 NJ
SD-31-0	3/18/2014	PCB-1254	<0.055 UJ
		PCB-1260	< 0.027
		PCB-1262	< 0.12
		PCB-1268	< 0.04
		Total PCBs	1.3
		PCB-1016	< 0.026
		PCB-1221	< 0.079
		PCB-1232	< 0.026
	2/10/2014	PCB-1242	< 0.046
CD 22.0		PCB-1248	0.79 NJ
SB-32-0	3/18/2014	PCB-1254	<0.028 UJ
		PCB-1260	< 0.013
		PCB-1262	< 0.059
		PCB-1268	< 0.02
		Total PCBs	0.79

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	< 0.026
SB-33-0		PCB-1221	< 0.081
		PCB-1232	< 0.026
		PCB-1242	< 0.047
	3/18/2014	PCB-1248	0.7 NJ
	3/18/2014	PCB-1254	<0.029 UJ
		PCB-1260	< 0.014
		PCB-1262	< 0.06
		PCB-1268	< 0.02
		Total PCBs	0.7
		PCB-1016	< 0.11
		PCB-1221	< 0.32
		PCB-1232	< 0.11
		PCB-1242	< 0.19
GD 24.0	2/10/2014	PCB-1248	4.1 NJ
SB-34-0	3/19/2014	PCB-1254	<0.11 UJ
		PCB-1260	< 0.055
		PCB-1262	< 0.24
		PCB-1268	< 0.082
		Total PCBs	4.1
		PCB-1016	< 0.027
		PCB-1221	< 0.084
	0/10/2014	PCB-1232	< 0.028
		PCB-1242	< 0.049
GD 25 0		PCB-1248	1 NJ
SB-35-0	3/19/2014	PCB-1221 PCB-1232 PCB-1248 PCB-1248 PCB-1254 PCB-1260 PCB-1262 PCB-1268 Total PCBs PCB-12121 PCB-1221 PCB-1242 PCB-1248 PCB-1242 PCB-1248 PCB-1260 PCB-1260 PCB-1260 PCB-1262 PCB-1262 PCB-1268 Total PCBs PCB-1268 Total PCBs PCB-12121 PCB-1221 PCB-1221	<0.03 UJ
SB-35-0		PCB-1260	< 0.014
		PCB-1262	< 0.062
		PCB-1268	< 0.021
		Total PCBs	1
		PCB-1016	<0.1
		PCB-1221	< 0.32
		PCB-1232	<0.1
		PCB-1242 <0	< 0.19
SB-40-0	3/18/2014	PCB-1248	<0.11 UJ
		PCB-1254	3.6 NJ
		PCB-1260	< 0.054
		PCB-1262	< 0.24
		PCB-1268	< 0.081
		Total PCBs	3.6

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	< 0.026
		PCB-1221	< 0.078
		PCB-1232	< 0.026
		PCB-1242	< 0.046
SB-41-0	3/19/2014	PCB-1248	<0.028 UJ
3D-41-0	3/19/2014	PCB-1254	0.52 NJ
		PCB-1260	< 0.013
		PCB-1262	< 0.058
		PCB-1268	< 0.02
		Total PCBs	0.52
		PCB-1016	< 0.053
		PCB-1221	< 0.16
		PCB-1232	< 0.054
		PCB-1242	< 0.095
SB-42-0	2/20/2014	PCB-1248	1.8 NJ
SB-42-0	3/20/2014	PCB-1254	<0.058 UJ
		PCB-1260	< 0.028
		PCB-1262	< 0.12
		PCB-1268	< 0.041
		Total PCBs	1.8
		PCB-1016	<5
	2/20/2014	PCB-1221	<15
		PCB-1232	<5
		PCB-1242	<8.9
GD 42.0		PCB-1248	160 NJ
SB-43-0	3/20/2014	PCB-1221 PCB-1232 PCB-1242 PCB-1248 PCB-1254 PCB-1260 PCB-1262 PCB-1268 Total PCBs PCB-1221 PCB-1221 PCB-1242 PCB-1242 PCB-1248 PCB-1242 PCB-1248 PCB-1254 PCB-1260 PCB-1260 PCB-1260 PCB-1262 PCB-1268 Total PCBs PCB-1016 PCB-12121 PCB-1221 PCB-1248	<5.4 UJ
5 D 43 0		PCB-1260	<2.6
		PCB-1262	<11
		PCB-1268	<3.8
		Total PCBs	160
		PCB-1016	< 0.052
		PCB-1221	< 0.16
		PCB-1232	< 0.052
			< 0.092
CD 44.0	3/20/2014	PCB-1248	2.3 NJ
SB-44-0		PCB-1254	<0.056 UJ
		PCB-1260	< 0.027
		PCB-1262	< 0.12
		PCB-1268	< 0.04
		Total PCBs	2.3

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	<52
		PCB-1221	<160
		PCB-1232	<53
SB-45-0		PCB-1242	<94
	3/19/2014	PCB-1248	1900 NJ
		PCB-1254	<57 UJ
		PCB-1260	<27
		PCB-1262	<120
		PCB-1268	<41
		Total PCBs	1900
		PCB-1016	<2.6
		PCB-1221	<8.1
		PCB-1232	<2.7
		PCB-1242	<4.7
SD 46.0	2/10/2014	PCB-1248	77 NJ
SB-46-0	3/19/2014	PCB-1254	<2.9 UJ
		PCB-1260	<1.4
		PCB-1262	<6
		PCB-1268	<2.1
		Total PCBs	77
		PCB-1016	<2.7
		PCB-1221	< 8.2
		PCB-1232	<2.7
	2/20/2014	PCB-1242	<4.8
CD 47 0		PCB-1248	110
SB-47-0	3/20/2014	PCB-1221 PCB-1232 PCB-1248 PCB-1248 PCB-1254 PCB-1260 PCB-1262 PCB-1268 Total PCBs PCB-1221 PCB-1232 PCB-1242 PCB-1254 PCB-1260 PCB-1260 PCB-1260 PCB-1260 PCB-1262 PCB-1262 PCB-1262 PCB-1268 Total PCBs PCB-12168 Total PCBs	<2.9
3 D- 47-0		PCB-1260	<1.4
		PCB-1262	<6.1
		PCB-1268	<2.1
		Total PCBs	110
		PCB-1016	< 0.0052
		PCB-1221	< 0.016
		PCB-1232	< 0.0052
		PCB-1242	< 0.0093
CD 40 0	3/20/2014	PCB-1248	0.15 NJ
SB-48-0		PCB-1254	<0.0056 UJ
		PCB-1260	< 0.0027
		PCB-1262	< 0.012
		PCB-1268	< 0.004
		Total PCBs	0.15

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	< 0.11
		PCB-1221	< 0.32
		PCB-1232	< 0.11
		PCB-1242	< 0.19
SB-49-0	3/20/2014	PCB-1248	3.5 NJ
SD-49-0		PCB-1254	<0.11 UJ
		PCB-1260	< 0.055
		PCB-1262	< 0.24
		PCB-1268	< 0.082
		Total PCBs	3.5
		PCB-1016	<100
		PCB-1221	<310
		PCB-1232	<100
	3/20/2014	PCB-1242	<180
SB-50-0		PCB-1248	3900 NJ
SD-30-0		PCB-1254	<110 UJ
		PCB-1260	<53
		PCB-1262	<230
		PCB-1268	<79
		Total PCBs	3900
		PCB-1016	< 0.55
SB-51-0		PCB-1221	<1.7
		PCB-1232	< 0.55
		PCB-1242	< 0.98
	3/20/2014		12 NJ
	3/20/2014		<0.59 UJ
		PCB-1260	< 0.29
		PCB-1262	<1.2
		PCB-1268	< 0.42
		Total PCBs	12

table 7 Analytical Laboratory Results for Concrete Samples

Stage I Investigation, Moline Street PCB Site

Sample Location	Collection Date	Analyte	TestAmerica Analytical Results (mg/kg or ppm)
		PCB-1016	<2.7
SB-52-0		PCB-1221	<8.2
		PCB-1232	<2.7
		PCB-1242	<4.8
	3/20/2014	PCB-1248 1 1	110 NJ
	5/20/2014	PCB-1254	<2.9 UJ
		PCB-1260	<1.4
		PCB-1262	<6.1
		PCB-1268	<2.1
		Total PCBs	110

Notes:

bolded values are detections; shaded entries indicate that concentrations that exceed 25 ppm. Yellow denotes a potential exceedance, as the detection limit exceeded the action level, whereas gray denotes a detected exceedance.

mg/kg = milligrams per kilogram

PCB = polychlorinated biphenyl

ppm = parts per million

< = analyte was not detected above the specified method detection limit Validation Flags: NJ - Tentatively Identified, U - Nondetect, UJ - Estimated Nondetect

STAGE I SUMMARY TECHNICAL MEMORANDUM Moline Street PCB Site

FIGURES











